	-		-	put all promises in writing. Keep this form.	
Buick	Encore G	-	-	KL4MMDSLXPB003310	
		YEAR		VEHICLE IDENTIFICATION NUMBER (VIN)	
WARRANTIES	S FOR THIS VEHICI	LE:			
				/ARRANTY	
THE DEAL	ER DOES NOT PROVIDE	\ WARRANT` -	Y FOR ANY F	REPAIRS AFTER SALE.	
	ALER WA	RRA			
□ FULL WAR	RANTY.				
that fail dur explain wa	ing the warranty period. As	k the dealer f and the deal	for a copy of t	<u>100</u> % of the parts for the covered systems he warranty, and for any documents that ligations. <i>Implied warranties</i> under your	
SYSTEMS COVERED:			DURATION:		
ENGINE			1,000 miles		
TRANSMISSION			1,000 miles		
POWER STEERING			1,000 miles		
AIR CONDITIONING			1,000 miles		
	akes, tires, or alignments ARE NOT				
NON-DEALER	WARRANTIES FOR	R THIS VE	EHICLE:		
		PLIES. The	manufacturer	's original warranty has not expired on some	
	ER'S USED VEHICLE WAR	ρανιτή αρρι	LIES		
	EHICLE WARRANTY APPI				
			volanation of v	varranty coverage, exclusions, and repair	
obligations.					
coverage, deduc		If you buy a	service contra	for an extra charge. Ask for details about act within 90 days of your purchase of this onal rights.	
	RIE YOUR MECHANIC CA			LE ON OR OFF THE LOT.	
OBTAIN A VEHICL how to obtain a veh	E HISTORY REPORT AN	D CHECK FO	OR OPEN SA	AFETY RECALLS. For information on for open safety recalls, visit safercar.gov. nake the best use of the resources on	
SEE OTHER SIDE	for important additional	information	, including a	a list of major defects that may occur in	
			, J		

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame **Engine**

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator Improperly functioning water pump

Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags**

Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning

Tires

Tread depth less than 2/32 inch Sizes mismatched

Visible damage

improperly

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

Exhaust System

Leakage Catalytic Converter

DEALER NAME	
AutoUSA, Ltd.	
ADDRESS 1316 E. Irving Blvd, Irving, TX	75060
TELEPHONE	EMAIL
972-438-9191	info@autousatexas.com
FOR COMPLAINTS AFTER SALE, CONTACT:	070 400 0404
Contact service department at	972-438-9191

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).